CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 783 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited

-	SECRET SECURITY INFORMATION		25X1
COUNTRY	East Germany	REPORT NO.	
SUBJECT	Funkwerk Koepenick Production Difficulties at Plant II	DATE DISTR.	30 June 1953
	Difficulties at Flant II	NO. OF PAGES	1
DATE OF INFO.	Prior to 19 May 1953 25X1	REQUIREMENT NO.	25X1
PLACE ACQUIRED		REFERENCES	
	THE SOURCE EVALUATIONS IN THIS REP THE APPRAISAL OF CONTENT IS (FOR REY SEE REVERSE	TENTATIVE.	

- 1. The production of rotary indicators (Drehmelder) at Plant II of Funkwerk Berlin-Koepenick is to be tripled in 1953 over last year's production. Production in 1952 was 1,400 pieces; in 1953 it is to be 4,000.
- 2. The main bottleneck is production is the shortage of good steel. This has made it impossible for some time to deliver equipment on schedule. Under microscopic examination the balls in the ball bearings were found not to be round, but angular and without smooth surfaces.
- 3. Dynamo sheets for oscillators present another difficulty. Five hundred oscillators had to have defective dynamo sheets annealed in a difficult and expensive process at a cost of 1,500 DM. This prevented delivery of the oscillators on time.

SECRET/

STATE X ARMY X NAVY X AIR X FBI AEC ORR EV X

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)